Owner Name and Address: Ted Svoboda Mile Marker 37 Highway 212 Box 26 Alzada MT 59311 Phone: (406) 828-4551

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
0610229	Valley Inn Bar & Cafe	US Highway 212	Alzada	59311	(406) 828-4551

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Temporarily Out of U		1/19/1988 18 / No	Diesel 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH) JKU	No Yes Yes Yes
2 / 02 Temporarily Out of U		1/19/1988 18 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH (J) (K) (L) (D) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B	No Yes Yes Yes
3 / 03 Temporarily Out of U		1/19/1988 18 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL • • EFGHIJKL	No Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 6

Owner Name and Address: William Walker Highway 212 Walker Subdivision PO Box 74 Alzada MT 59311 Phone: (406) 828-4400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613910	B & J Convenience Store	US Highway 212	Alzada	59311	(406) 828-4400	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
1 / 01 Currently In Use	3564	12/1/1998 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.H.I.J.K.L B DEFGHI.K.L	Yes Yes Yes Yes
2 / 02 Currently In Use	3565	12/1/1998 07 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	(A B C D E F • H ) J K L B D E F G H ) • K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 6

Owner Name and Address: Carter County Commissioners 214 Park St PO Box 315 Ekalaka MT 59324 Phone: (406) 775-8749

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0600863	Hospital Courthouse	101 Park St	Ekalaka	59324	(406) 775-8749

TankiD/Alt TankiD Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
2 / S3 Currently in Use	532	7/1/1991 15 / No	Heating Oil 6,000	STI-P3 Excavation Liner	Bare Steel Cathodically Protected	U.S. Suction	ABCDEFGBIJKL B D@FGHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 6

Owner Name and Address: Fruit Service & Repair Inc PO Box 318 Ekalaka MT 59324 Phone: (406) 775-6541

Sys Fac I	Location Name	Location Street Address	Loca	tion City Zip	Location Phone	
0601681	Fruit Service & Repair Inc Main St	40 Main St	Ekala	ka 59324	(406) 775-6541	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
3 / 03 Currently in Use	1132	4/26/1990 16 / No	Gasoline 1,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	8 DEFGHIJKL  B DEFGHI•KL	Yes Yes Yes Yes
4 / 04 Currently in Use	1133	4/26/1990 16 / No	Gasoline 1,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<b>ABCDEF●HJ&amp;L B DEFGHJ&amp;L</b>	Yes Yes Yes Yes
5 / 05 Currently in Use	1134	4/26/1990 16 / No	Diesel 1,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF.HIJKL B DEF.HI.KL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 6

Owner Name and Address: Fruit Service & Repair Inc PO Box 318 Ekalaka MT 59324 Phone: (406) 775-6541

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0603234	Fruit Service & Repair Inc SR 323	31 MT Highway 323	Ekalaka	59324	(406) 775-6541

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
6 / 06 Currently In Use	3617 4	4/1/1998 08 / No	Diesel 5,565	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	ABCDEF®HIJKL B DEFGHI•KL	Yes Yes Yes Yes
7 / 07 Currently In Use	1135 4	1/1/1998 08 / No	Diesel 4,590	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	ABCDEF.H.I.J.K.L B. DEF.G.H.I.J.K.L	Yes Yes Yes Yes
8 / 08 Currently In Use	1136 4	1/1/1998 08 / No	Gasoline 2,365	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	ABCDEF.H.I.J.K.L B. DEF.G.H.I.J.K.L	Yes Yes Yes Yes
9 / 09 Currently In Use	1137 4	4/1/1998 08 / No	Gasoline 9,627	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	(ABCDEF.H)JKL B DEF.GH)•KL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 6

Owner Name and Address: Ekalaka Elementary School Dist 15 106 E Park PO Box 458 Ekalaka MT 59324 Phone: (406) 775-8765

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
0604710	Ekalaka Elementary School	102 Park St	Ekalaka	59324	(406) 775-8767

TankiD/Alt TankiD Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/CP
2 / S2 Currently in Use	859 8	3/1/1991 14 / No	Heating Oil 6,000	Cathodically Protected Steel Excavation Liner	Flexible Plastic Double-Walled	Safe Suction	(ABCDEFGETURU B DEFOHTOKU	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 6